

From: 8064986673

To: USPTO

Page: 5/13

Date: 2005/9/16 上午 08:37:50

Appl. No. 10/707,560
Amdt. dated September 16, 2005
Reply to Office action of June 22, 2005

Amendments to the Specification:

Please replace the original title with the following new title:

5 METHOD OF REPAIRING PIT DEFECT AND SALIENT DEFECT OF
ELECTRODE PATTERN